### ATTACHMENT J

#### Industrial Products United States Gypsum Compa 125 South Frankin Street Chicago, IL 60806

1W858-3007.43 ©2003, United States Appsum Compa Printed and Produced in U.S.A. http://www.usq.com

## FRAGILE-DO NOT DROP

INGREDIENTS Man-frade mineral fiber CAS 65997-17-3; expanded perlite CAS 93763-70-3; recycled paper (cellulose) CAS 9004-34-6; and starch CAS 9005-25-8. May contain kaclin CAS 1332-59-7, which contains crystalline silica CAS 14808-60-7.

Mineral Fiber Board

#### AWARKING

Alst hazard. Cut and trim with knife, razor or hand saw. Do not cut with power equipment unless a dust collector is used on the equipment or local educats is used and a NiOSHANSHA-approved respirator is worn. Faiure to follow these instructions may result in overexposure to althorne man-made mineral floer. Althorne man-made mineral floer and crystalline silica are trought to increase the risk of lung cance. Overexposure to dust can cause eye, skin, nose, throat or respiratory initiation. Viear eye and skin protection.



**FIRST AID** For skin Irritation, rinse with coal water, fellowed by washing with soap and warm water. For eye Inflation, flush eyes thoroughly with water for 15 minutes. If Inflation pensists, cossuit a physician. Product safety information: (800, 507-8899.).

# TRIS PRODUCT CONTAINS NO ASBESTOS

NAVOLING Protect from impact and abreaton to avoid damage to all edges.

**HISTALLATION** Store and Install at standard occupancy conditions (lemperature 60° to 85° P) and relative furnidity (below 70% for at least 24 hours prior to installation). Extreme changes in 1910 perature or humidity may cause panels to expand, contract or warp.